

## METALLIC™

### THE MOST ADAPTED METALLIC EFFECT HEAT TRANSFER FILM FOR ACCESSORIES PERSONALISATION

Looking for a special metallic effect? Metallic is a PU film with a super glossy metallic look.

#### Fashion accessories



#### Home decor



#### Product description

- ✓ Great glossy metal finish.
- ✓ Very thin → Comfortable to wear.
- ✓ Perfect for weightless textiles thanks to its thinness.
- ✓ Available in 9 metallic colours and 1 holographic metallic effect:



Super Silver 420



Super Gold 421



Super Red 437



Super Fuchsia 460




Super Blue 435



Super Bronze 461




Super Green 436



Super Zinc 462



Copper 438



Super Rainbow 422

#### Application key points

- ✓ Very easy to cut.
- ✓ Easy to weed → saves production time.
- ✓ Qualitative metallic visual effect without wrinkled finish.

#### Usage benefits

- ✓ Recommended for adding decorative details to fashion and home deco accessories.
- ✓ Perfect for very small and precise designs.
- ✓ Clean finish with no glue excess.

## SPECIFICATIONS

Composition	Average Thickness	Carrier	Dimensions
PU	60 µm	Adhesive & Transparent Polyester	<b>All references available in:</b> 48cm x 5 m <b>Ref 420 &amp; 421</b> also available in: 48 cm x 10/20 m 36/145 cm x 20 m

## APPLICATION INSTRUCTIONS

Applies on	Cutting	Application Temp. & Duration
Acrylic Cotton/Polyester blends without repellent treatment	Flex Blade 45°	145°C – 15 s 293°F – 15 s

Pressure	Peeling
Medium	Cold

**Step 1 – Cutting**

Set up the cutting of your heat transfer film in mirror mode and use a standard flex blade of 45°.

**Step 2 – Weeding**

Remove the excess of material (easy weeding).

**Step 3 – Application**

Position your design on the textile and press it with a Sefa DUPLEX/ROTEX or equivalent at 145°C/293°F for 15 seconds with a medium pressure.

We do recommend the use of a silicone paper to protect the designs and the textile during the application.

**Step 4 – Peeling**

Peel the material when cold.

*NOTE: We highly recommend you to perform tests before launching a production.*

## CARE AND MAINTENANCE RECOMMENDATIONS

Washing	Ironing	Tumble-dry	Dry cleaning
Hand washing only	On reverse side only	Not recommended	Not recommended

**Care and maintenance:**

- ✓ Always respect the garments' instructions.
- ✓ Wait 24 hours after the application before the first wash.
- ✓ Avoid the use of aggressive products.

Storage life	Storage Temperature & Lightning	Position
Up to 1 year	Dry room with 15°C-30°C/ 59°F-86°F	Away from sunlight Vertical position

**Washing recommendations:**

- ✓ Respect the textile recommendations.
- ✓ Preferably inside out to extend the design's life.
- ✓ Do not bleach.